



OFFICE OF THE MUNICIPAL COUNCIL:: NALGONDA

STRUCTURAL SOUNDNESS CERTIFICATE

Dated: 17/7/2019

This is to certify that the school Building of Little Flower CBSE innovative school Nalgonda Bearing Door.No.5-11-3/a situated at Devarakond road, Nalgonda Town & District Is in Good Condition and soundness of the building is SATISFACTORY.

Commissioner
Nalgonda
COMMISSIONER
NALGONDA MUNICIPALITY

To

Correspondent
Little Flower CBSE innovative school
Devarakond road
Nalgonda